


KNOW HOW TO ORDER



Thread size

- 10 : Thread part G1/8 thread
- 20 : Thread part G1/4 thread
- 30 : Thread part G3/8 thread




Design no.

1 : Revision Number


Control method

- M Meter IN
- N Meter OUT

M



N



Specifications

Model	SCV0101-M	SCV0101-M	SCV0101-M	SCV0101-N	SCV0201-N	SCV0301-N
Max operating pressure Mpa	35			7		
With standing pressure Mpa	40			10		
Control method	Meter - IN			Meter - OUT		
G thread size	G1/8	G1/4	G3/8	G1/8	G1/4	G3/8
Cracking pressure	0.04					
Operating temprature	0~70					
Recomanded tightening torque for main body N.m	10	25	40	10	25	40